

#1160 - Willmar

10/21/2026 at 6:22 PM | Intersection of 4th street and monongalia. North west corner of intersection

Status: Open**JOB & TIMING**

Job number	#1160 - Willmar
Date of damage	10/21/2026
Time of damage	6:22 PM
Form filled out	10/21/2026
Submitted	10/21/2026 7:40 PM
Person filling out form	Joseph
Foreman on the job	Joseph Rooney

OFFICE NOTIFICATION

Date office notified	10/21/2026
Method of notification	Cell
Who was contacted	Orry Wiechman

UTILITIES HIT

Location of utility hit	Intersection of 4th street and monongalia. North west corner of intersection
-------------------------	--

Fiber - Centra care

Utility notified	Yes
Company arrived onsite	No
GSOC #	-
Most recent locate	-
How it was marked	Paint, Flag
Marks accurate or off	The paint and flags were disturbed from previous digging.

WHAT HAPPENED

Summary of incident	We were removing an existing catch basin and the conduit was under the slab of the catch basin. The slab was sitting on top of the conduit
Are we at fault?	Yes
Why?	We dug around the conduit earlier in the day and we knew it was there.
Utility said we are NOT responsible?	No

PHOTOS (7)

Pictures taken by	Joseph Rooney
-------------------	---------------



Photo 1 of 7 - uploaded 10/21/2026 7:39 PM



Photo 2 of 7 - uploaded 10/21/2026 7:39 PM



Photo 3 of 7 - uploaded 10/21/2026 7:39 PM



Photo 4 of 7 - uploaded 10/21/2026 7:39 PM



Photo 5 of 7 - uploaded 10/21/2026 7:39 PM



Photo 6 of 7 - uploaded 10/21/2026 7:39 PM



10/21/2026 7:39 PM
#1160 - Willmar - RYAN CONTRACTING

Photo 7 of 7 - uploaded 10/21/2026 7:39 PM

SIGNATURE

Signed by Joseph on 10/21/2026

CLAIM HISTORY

Open 10/21/2026 7:40 PM - Joseph
Report filed from the field.